

Certificate IATF 0574579
SGS Certificate number DE25/00000375.05
The management system of
tesa Brasil Ltda.

IATF USI: L2HSR5
Parque Industrial, Rua Anhanduí, 520, Galpão 7F, Flores, Manaus, AM, 69058-827, Brazil

has been assessed and certified as meeting the requirements of

IATF 16949:2016

Edition 1

For the following scope
Design and manufacturing of self-adhesive tapes.

EXCLUSIONS : None

3 Year certification is valid from 02 June 2025 until 01 June 2028 and remains valid subject to satisfactory surveillance audits.

Version no. 2. Current version updated 04 August 2026



Authorised by
Harikant Mudgal
Technical reviewer
Contracted Office : SGS United Kingdom Ltd, Station Road, Oldbury, B69 4LN, UK.
Email : Neil.Hall@sgs.com



This document is an authentic electronic certificate for Client' business purposes use only. Printed version of the electronic certificate are permitted and will be considered as a copy. This document is issued by the Company subject to SGS General Conditions of certification services available on [Terms and Conditions | SGS](#). Attention is drawn to the limitation of liability, indemnification and jurisdictional clauses contained therein. This document is copyright protected and any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful.



tesa Brasil Ltda.

IATF 16949:2016

Edition 1

Additional facilities

Stand-Alone Remote Support Location (SA-RSL)

tesa SE

IATF USI: L59H5T

Hugo-Kirchberg-Straße 1, 22848 Norderstedt, Germany

Summary of Activities

Packaging, Product Design, Management Review, Customer Service, Logistics, Purchasing, Finance, Sales, Information Technology, Quality System Management, Internal Audit Management, Human Resources, Engineering, Distribution, Marketing, Research And Development, Policy Making, Strategic Planning, Contract Review, Supplier Management

Stand-Alone Remote Support Location (SA-RSL)

tesa Brasil Ltda.

IATF USI: P3Z5C4

Ave. João Gualberto, no. 1259 - 18th/19th Floor, Centro Empresarial Lais Peretti, Alto da Gloria, Curitiba, PR, 80030-000, Brazil

Summary of Activities

Management Review, Customer Service, Logistics, Finance, Sales, Internal Audit Management, Human Resources, Engineering, Supplier Management

Stand-Alone Remote Support Location (SA-RSL)

tesa tape Argentina S.R.L.

IATF USI: YKYTHW

Arias 1639, Piso 21, esquina Av. Libertador, C1429BMP, Ciudad Autónoma de Buenos Aires, Argentina

Summary of Activities

Customer Service, Sales, Distribution



This document is an authentic electronic certificate for Client' business purposes use only. Printed version of the electronic certificate are permitted and will be considered as a copy. This document is issued by the Company subject to SGS General Conditions of certification services available on [Terms and Conditions](#) | SGS. Attention is drawn to the limitation of liability, indemnification and jurisdictional clauses contained therein. This document is copyright protected and any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful.



Certificate IATF 0574579, continued
SGS Certificate number DE25/00000375.05

SGS

tesa Brasil Ltda.

IATF 16949:2016

Edition 1

Additional facilities

Stand-Alone Remote Support Location (SA-RSL)

tesa Brasil Ltda.

IATF USI: 3E3W4E

Alameda Bom Pastor, 3250, Conj. Módulo Tesa, Barro Preto, São José dos Pinhais, PR, 83015-810, Brazil

Summary of Activities

Distribution



This document is an authentic electronic certificate for Client' business purposes use only. Printed version of the electronic certificate are permitted and will be considered as a copy. This document is issued by the Company subject to SGS General Conditions of certification services available on [Terms and Conditions | SGS](#). Attention is drawn to the limitation of liability, indemnification and jurisdictional clauses contained therein. This document is copyright protected and any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful.

